

1/4

Fig. 1a




Fig. 2a




Fig. 3a




Fig. 1b




Fig. 2b




Fig. 3b




Fig. 1c



Fig. 2c




Fig. 3c




Fig. 4a




Fig. 5a




Fig. 6a




Fig. 4b



Fig. 5b



Fig. 6b





Fig. 4c



Fig. 5c



Fig. 6c



10018027-028001

2/4

Fig. 7




Fig. 8





Fig. 9



10018027 022800 208220 2208T00T

3/4

Fig. 10




Fig. 11






Fig. 12



10018027-022802

4/4

Fig. 13



10018027-022800F